

"Thornhill" (Tom Welch)  
2 mi. S. Talladega, Ala.  
Sylacauga Highway  
TALLADEGA Co

HABS No. ALA-441

HABS  
ALA.  
61-TALA.V

PHOTOGRAPHS  
WRITTEN HISTORIC AND DESCRIPTIVE DATA  
DISTRICT NO.16

Historic American Buildings Survey  
E. Walter Burkhardt, District Officer  
Auburn, Alabama

Additional Data: The old family grave-yard is about one hundred yards south west of the house and contains tombs of the original family.  
 John Hardie. Born 1797, Died 1848.  
 Mary Mead Hardie, daughter of Rev. Isaac Hall, and wife of John Hardie. Born 1812, Died 1872.  
 Annie Hardie, daughter of John and Mary M. Hardie, and wife of J. M. Lewis. Born 1846, Died 1880.  
 Mary A. Hardie, wife of John H. Lewis. Born 1807, Died 1916.  
 William Hudson, son of John and Sarah Hudson, Born 1831, Died 1853.  
 Helen Hardie Spence, daughter of John Hardie and wife of William Spence, Died 1886.

Source of Material: W. A. Green.  
 Talladega, Alabama.

Compiled by: Katherine Floyd.  
 Auburn, Alabama.  
 J. B. Vaughn.  
 Birmingham, Alabama.  
 Approved: E. Walter Burkhardt, District Officer, HABS  
 Auburn, Alabama.  
 Date: 61- 31- 1936.

Rev. Oct 9. 36 - H.E.

THORN HILL (Residence)  
Two miles south of Talledega,  
Talledega, Talledega County, Alabama.

Ownership:

Present Owner: T.L. Welch.  
Previous Owners: T. H. Lewis. From 1880 to 1905.  
J. M. Lewis. From 1848 to 1880.  
John Hardie. From 1835 to 1848.

Date of Erection: 1835.

Architect: Unknown.

Builder: John Hardie.

Present Condition: Very good state of preservation. However the place being rented, it is not kept in good repair. About twenty five years ago the original kitchen was joined to the left rear of the house, and a back hall was made of the back porch.

Material of Construction: Frame structure, with wood shingle roof. The exterior walls are of 6" heart of pine weather-boarding. The foundation is of brick pillars covered with concrete. It has three exterior chimneys, also four 18" square columns to the front. There is a small balcony over the front door with wooden railings. The ceiling to the porch is plastered. The original porch has been replaced. The interior walls were replastered about fourteen years ago. The stairway ascends the right of the hall to a landing, across the rear, ascending the left of the hall to the second floor.

Other Existing Records:

ALA. 61-TALA.V, 1-1

HAB5



ALA441



ALA441

ALA. U. TALA.V , 1-2

7231WYH—WIBVIL—KUDVA

102

HABS



ALA441



ALA 441



ALA 441

ALA., GI. TALA.V., LA-1-S HABS

45



ALA., BI-TALA.V., 1-6

HABS



ALA 441



ALA441



ALA. 61 TALA V. 164

HAB 5